

United States Environmental Protection Agency  
Region 5

IN THE MATTER OF:	)	
	)	
JAY EM AEROSPACE	)	FINDING OF VIOLATION
Cuyahoga Falls, Ohio	)	
	)	EPA-5-00-OH-18
	)	
Proceedings Pursuant to	)	
the Clean Air Act,	)	
42 U.S.C. §§ 7401 <u>et seq.</u>	)	

---

**FINDING OF VIOLATION**

The United States Environmental Protection Agency finds that Jay Em Areospace (JM) is violating Section 112 of the Clean Air Act, 42 U.S.C. § 7412. Specifically, JM is violating the National Emission Standards for Hazardous Air Pollutants (NESHAP) for Halogenated Solvent Cleaning at 40 C.F.R. Part 63, Subpart T as follows:

**Regulatory Authority**

1. The NESHAP for Halogenated Solvent Cleaning applies to solvent cleaning machines that use any of the following halogenated solvents: methylene chloride, perchloroethylene, trichloroethylene, 1,1,1,- trichloroethane, carbon tetrachloride, and chloroform, or and combination of these halogenated solvents in a total concentration of greater than 5 percent by weight, as a cleaning and/or drying agent.
2. The NESHAP, at 40 C.F.R. §§ 63.460-469, requires the owner and operator of solvent cleaning machines to minimize emissions from their operations.

**JM's Facility**

3. JM owns and operates a batch vapor cleaning machine at 75 Marc Avenue, Cuyahoga Falls, Ohio.
4. JM's Marc Avenue facility is subject to the requirements at 40 C.F.R. § 63.460(a). The facility installed the batch vapor

cleaning machine prior to November 29, 1993. This meets the definition of an existing batch vapor cleaning machine. The existing batch vapor cleaning machine uses trichloroethylene in a total concentration greater than 5% by weight as its cleaning agent. 40 C.F.R. §63.460(a).

5. The facility is required to achieve compliance with the provisions of 40 C.F.R. Subpart T no later than December 2, 1997.

6. The facility complies with the alternative standards at 40 C.F.R. § 63.464 for its existing batch vapor cleaning machine.

7. The facility was required to submit an initial notification report for its existing batch vapor cleaning machine on or before August 29, 1995. 40 C.F.R § 63.468(a).

8. The facility was required to submit an initial statement of compliance no later than 150 days after the compliance date of December 2, 1997, for its existing batch vapor cleaning machine. 40 C.F.R. § 63.468(e).

9. On March 16, 2000, a U.S. EPA inspector inspected JM's facility located at 75 Marc Avenue, Cuyahoga Falls, Ohio for compliance with 40 C.F.R. Part 63 Subpart T.


#### Violations

10. From August 29, 1995 to present, in violation of 40 C.F.R. § 63.468(a), JM failed to submit an initial notification report to the Administrator for its existing batch vapor cleaning machine.

11. From May 1, 1998 to present, in violation of 40 C.F.R. § 63.468(e), JM failed to submit an initial statement of compliance to the Administrator no later than 150 days after the specified compliance date of December 2, 1997.

Date

6/30/00

  
Bharat Mathur, Director  
Air and Radiation Division

CERTIFICATE OF MAILING

I, Loretta Shaffer, certify that I sent a Finding of Violation,  
No. EPA-5-00-OH-18, by Certified Mail, Return Receipt Requested, to:


Greg Norman, President  
Jay Em Aerospace  
75 Marc Avenue  
Cuyahoga Falls, Ohio

I also certify that I sent copies of the Finding of Violation by  
first class mail to:

Robert Hodanbosi, Chief  
Division of Air Pollution Control  
Ohio Environmental Protection Agency  
Lazarus Government Center  
P.O. Box 1049  
Columbus, Ohio 43216-1049

Lynn Malcolm  
Akron Regional Air Quality District  
Management District  
146 S. High Street  
Room 904  
Akron, Ohio 44308

on the 6 day of July, 2000.

  
Loretta Shaffer, Secretary  
AECAS, (MN/OH)

CERTIFIED MAIL RECEIPT NUMBER: P140 897021